_ Approved For Release 2001/07/27 : CIA-ROP81B00879R001000030082-2

CEC - 1038 Cour eof 6

7 Movember 1960

MEXICOLARDEN FOR , Chief, Development Branch, DPD-DD/P

SULLEGT.

25X1A

: CICART Special Equipment Suilding Recognizacionts for

l. The building to house all special equipment activities and processing facilities must have approximately nine to ten thousand square feet of floor space and be dust free and air conditioner. Details and building requirements are as follows for your information and guidence;

A. Londing Areas

- (1) Two loading areas must be provided. Sach loading area must be empable of accepting the forward portion of an A-12. Each area most be deep enough to singustaly clear the aft Q-bay bulkheed when doors are slowed around the sircraft.
- (2) Both loading areas must have persupent drains for washing the 1-12 and floors of the area to keep dust and dirt at a minimum.

B. Heintenance and Storege Areas:

- (1) Sevironment temperature must be maintained in all areas other then film storage at 70°F plus or stone 5".
- (2) Bundity must be maintained at 90% MM, plus or minus %.
- (3) Bust and dirt control: Positive pressure must be maintained throughout the complete building to include loading areas and pressure must be 1/6 to 1/4 percents. It is desired to maintain cleanliness of s building in such a marmor that all particles of dust and dirt greater than 25 microns are reserved.

DOCUMENT NO. -NO CHANGE IN CLASS. DEGLASSIFIED CLASS. CHANCEL TO: TS S O MEXT REVIEW MATER -

Approved For Release 2001/07/27 : CIA-RDP81B00879R00490630082-2 : R: 064540

OCC-1036 Page 2

- (4) Lightingt Incomission lights will be installed in all areas except offices, analysis resss and A-12 loading areas. These areas may be equipped with fluorescent lighting.
- (5) Ploores All flours other than A-12 losding areas will be asphalt or rubber tile floore.
- (6) Walls and estlings: All walls and estlings will be of a smooth hard finish. There will be no windows in any part of the building.
- C. Film Storage Arcest
 - (1) Temperature 50°F plus or minus 5°F.
 - (2) Bondity 50% BE plus or minus 5%.
- (3) Dust and dirt sentrol same as for maintenance and storage areas.
- 2. It is full that a filter system composed of Cambridge Asresolve 35 filters or equal sheed of the air conditioner and Cambridge Asresolve 85 filters or equal after the airconditioner will be adequate to satisfy the dirt and dust requirements outlined above.
- 3. The attached layout showing loading, maintenance, proceeding areas and film storage is natiafactory if we are to have three camera contractors occupying the building at the same time. It is felt that this may be an unsatiafactory arrangement and require too many people. Although each contractor is going to insist on maintaining their own equipment, consideration might be given to having one contractor maintain the equipments for all three, that is, Perkin-Elmer tech repetation the equipments for all three, that is, Perkin-Elmer tech repetation that maintain both Casteman-Sodak and Automotries equipments as well as their own.
- on which approach to take concerning contractor tech rape for the special manifestation. If one contractor is to maintain all special manifestations desirable to change the attached floor plant equipments. It would be desirable to change the attached floor plant.
- it is highly recommended that a project non be placed in charge of the special equipments section to supervise and direct all activities in support of operations. It is recommended thus be a military man, hajor, APSC, 2316, photographic and cartographic officer.

Charles Sail